MEMORANDUM

TO: LINDSAY MASTERS – COLORADO DEPARTMENT OF PUBLIC HEALTH

& ENVIRONMENT, HAZARDOUS MATERIALS & WASTE MANAGEMENT

DIVISION

FROM: TOM HARP - REMEDIATION RISK REDUCTION, LLC (R³)

SUBJECT: BI-WEEKLY STATUS UPDATE – THORNTON SHOPPING CENTER,

NORTHWEST CORNER $88^{\rm TH}$ AND CORONA, THORNTON, CO – EPA #COR000212639, M&E 3.2, THORNTON LLC (THORNTON SHOPPING

CENTER)

DATE: 3/10/2021


CC: THORNTON LLC

Lindsay;

Per the requirement stipulated in your June 23, 2020 correspondence, the *Bi-Weekly Status Update* for March 10, 2021 regarding the Thornton Shopping Center is as follows:

COMPANY/SUB CONTRACTOR	R ³ /Alpine Remediation, Inc.					
BOS 100 [®] INJECTED	BOS 100 [®] VOLUME (lbs.)	DEPTHS	DATE	SLURRY VOLUME (Tgal.)	INJECTION PRESSURE (psig.)	
OFS-2 (pt.3)	105	16',18',20',22',24'	2/24/2021	375	1200 - 300	
OFS-2 (pt.5)	150	16',18',20',22',24'	2/24/2021	375	1200 - 300	
OFS-2 (pt.4)	105	15',17',19',21',23'	2/24/2021	375	900 - 300	
OFS-2 (pt.1)	150	15',17',19',21',23'	2/24/2021	375	800 - 300	
OFS-2 (pt.7)	105	15',17',19',21',23'	2/24/2021	375	800 - 300	
OFS-2 (pt.2)	105	15',17',19',21',23'	2/24/2021	375	1200 - 300	
OFS-2 (pt.6)	105	15',17',19',21',23'	2/24/2021	375	900 - 500	
OFS-2 (pt.29)	105	15',17',19',21',23'	2/24/2021	375	1200 - 300	
OFS-2 (pt.28)	150	16',18',20',22',24'	2/24/2021	375	800 - 400	






OFS-2 (pt.33)	150	16',18',20',22',24'	2/26/2021	240	1200 - 300
OFS-2 (pt.30)	150	15',17',19',21',23'	2/26/2021	240	1200 - 300
OFS-2 (pt.31)	150	16',18',20',22',24'	2/26/2021	240	1200 - 400
OFS-2 (pt.32)	150	15',17',19',21',23'	2/26/2021	240	1200 - 500
NOTE: OFS-2 pts. 9, 12, 15, 18, 21, 24, and 26 were previously reported as having a BOS Volume of 105 lbs., but received 150 lbs.					
OFS-3 (pt.26)	93	16',18',20'	3/1/2021	225	1200 - 600
OFS-3 (pt.12)	-	-	3/1/2021	-	-
OFS-3 (pt.5)	62	15',17'	3/1/2021	150	1200 - 600
OFS-3 (pt.40)	155	15',17',19',21',23'	3/1/2021	375	1200 - 400
OFS-3 (pt.41)	155	16',18',20',22',24'	3/1/2021	375	1200 - 600
OFS-3 (pt.37)	116	16',18'	3/1/2021	150	1200 - 500
OFS-3 (pt.39)	290	16',18',20',22',24'	3/1/2021	375	1200 - 400
OFS-3 (pt.14)	116	16',18'	3/1/2021	150	1200 - 600
OFS-3 (pt.32)	155	16',18',20',22',24'	3/1/2021	375	1200 - 600
OFS-3 (pt.21)	93	15',17',19'	3/2/2021	225	1200 - 500
OFS-3 (pt.35)	155	15',17',19',21',23'	3/2/2021	375	1200 - 600
OFS-3 (pt.43)	62	15',17'	3/2/2021	150	1200 - 600
OFS-3 (pt.44)	62	16',18'	3/2/2021	150	1200 - 500
OFS-3 (pt.20)	93	16',18',20'	3/2/2021	225	1200 - 500
OFS-3 (pt.31)	62	15',17'	3/2/2021	150	1200 - 500
OFS-3 (pt.33)	93	15',17',19'	3/2/2021	225	1200 - 600







		1	T		1
OFS-3 (pt.30)	93	16',18',20'	3/2/2021	225	1200 - 500
OFS-3 (pt.17)	62	15',17'	3/2/2021	150	1200 - 500
OFS-3 (pt.16)	62	16',18'	3/2/2021	150	1200 - 400
OFS-3 (pt.24)	93	16',18',20'	3/3/2021	225	1200 - 400
OFS-3 (pt.13)	31	15'	3/3/2021	75	1200 - 500
OFS-3 (pt.10)	-	-	3/3/2021	-	-
OFS-3 (pt.9)	-	-	3/3/2021	-	-
NOTE: several injection depths in OFS-3 could not be completed due to refusal (discussed below).					
OFS-1 (pt.15)	280	15',17',19',21',23'	3/5/2021	375	900 - 450
OFS-1 (pt.19)	280	15',17',19',21',23'	3/5/2021	375	900 - 600
OFS-1 (pt.23)	280	15',17',19',21',23'	3/5/2021	375	800 - 300
OFS-1 (pt.26)	430	16',18',20',22',24'	3/5/2021	375	900 - 300
OFS-1 (pt.22)	-	-	3/5/2021	-	-
OFS-1 (pt.18)	56	16'	3/5/2021	75	600 - 300
OFS-1 (pt.25)	430	15',17',19',21',23'	3/5/2021	375	900 - 450
OFS-1 (pt.11)	280	15',17',19',21',23'	3/5/2021	375	1000 - 350
OFS-1 (pt.16)	280	16',18',20',22',24'	3/5/2021	375	1000 - 300
OFS-1 (pt.14)	280	16',18',20',22',24'	3/8/2021	375	1200 - 200
OFS-1 (pt.29)	430	15',17',19',21',23'	3/8/2021	375	1200 - 300
OFS-1 (pt.10)	280	16',18',20',22',24'	3/8/2021	375	1200 - 300
OFS-1 (pt.20)	280	16',18',20',22',24'	3/8/2021	375	1200 - 300



	I						
OFS-1 (pt.9)	280	15',17',19',21',23'	3/8/2021	375	1200 - 300		
OFS-1 (pt.24)	280	16',18',20',22',24'	3/8/2021	375	1200 - 300		
OFS-1 (pt.27)	430	15',17',19',21',23'	3/8/2021	375	1200 - 300		
	HIGHLIGHTED INJECTION POINTS ARE LOCATED ON THE UPGRADIENT BOUNDARY OF TREATMENT AREAS AND RECEIVED ADDITIONAL BOS 100® VOLUMES FOR PRB PURPOSES						
SUPPLEMENTAL SAMPLING	SAMPLES	DATE COLLECTED	DATE OF RESULTS				
OFS-3 (MW-18)	1	3/1/2021	pending				
OFS-2 (MW-20)	1	3/5/2021	pending				
OFS-1 (MW-19)	1	3/5/2021	pending				
OFS-5 (MW-24)	1	3/5/2021	pending				
SOLID WASTE GENERATED	NO. OF DRUMS SOIL	NO. OF DRUMS WATER	HAZARDOUS WASTE GENERATED	NO. OF DRUMS SOIL	NO. OF DRUMS WATER		
OFS-2	N/A						
OFS-3	N/A						
OFS-1	N/A						
OTHER PLANNED ACTIVITIES	ESTIMATED SCHEDULE	POTENTIAL ROADBLOCKS/ DELAYS					
CDPHE and Thornton LLC/Jay Brown agreed to a Joint Motion for Entry of Stipulated Injunction.	Phase I offsite installation to be completed by 3/15/2021. Phase II offsite installation to be completed by 6/1/2021.						




	I	T		
CDPHE requested that offsite wells MW-29, MW-30, and MW-31 (installed by RETTEW) be sampled in 2020.	12/08/2020			
R ³ collected groundwater samples from offsite wells MW-29, MW- 30, and MW-31.	12/10/2020			
R ³ submitted the Second <i>Semi-Annual</i> 2020 <i>Groundwater Monitoring Report Addendum</i> to the CDPHE for review and approval.	01/08/2021	Awaiting CDPHE response.		
R ³ commenced Phase I injections in Treatment Area OFS-2.	2/16/2021			
R ³ completed injections in Treatment Area OFS-2.	2/26/2021			
R ³ commenced Phase I injections in Treatment Area OFS-3.	3/1/2021			
R ³ ceased Phase I injections in Treatment Area OFS-3 due to refusal issues.	3/3/2021	Awaiting approval of alternative injection method, e.g., "predrilling" from CDPHE.		
R ³ took delivery of all BOS 100 for Phase I and Phase II.	3/4/2021			



R ³ commenced Phase I injections in Treatment Area OFS-1.	3/5/2021		
Thornton LLC and City of Thornton conferred to discuss current available options going forward with the development/ remediation of the Thornton Shopping Center.	3/10/2021		
Thornton LLC is working with Sterling Design design/architectural/ surveying team to subdivide the Shopping Center to sell additional parcels to developers. With that in mind, Thornton LLC is in discussion with real estate brokers and multiple potential users for the site to develop a subdivision plan that works more closely with their needs. Thornton LLC is conferring with potential purchasers of the complete Shopping Center; has received one offer and has made a counteroffer.	Ongoing		
built a construction			





fence around the			
vacant east buildings			
(8954 - 8988) to			
protect against			
vagrants prior to			
demolition, which is			
anticipated to occur			
after remediation of			
asbestos in the			
Spring of 2021.			
Thornton LLC is			
aware that any			
remediation will be			
done by a licensed			
contractor, per			
CDPHE			
requirements.			
Abatement permit			
has been obtained;			
beginning of			
abatement scheduled			
for March 18, 2021.			

I will notify you if there are any pending additions/deletions to this update. Please do not hesitate to contact me should you have any questions or require additional information.

Sincerely,

REMEDIATION RISK REDUCTION, LLC

Thomas A. Harp, P.G., M.S.C.E., M.B.A.

Thomas . Hans

Principal